MATERIAL SAFETY DATA SHEET BOOK PAGE: CHEMICAL ID: 437900 MSDS ID: 437900 PRODUCT NAME: Renuzit Fresh N Dry Air & Fabric Deodori

FACILITY: 316400 Northwest District

MATERIAL SAFETY DATA SHEET

SECTION I GENERAL INFORMATION

The Drackett Products Company

EMERGENCY CONTACT: (513)-632-1500

5020 Spring Grove Ave. Cincinnati, Ohio 45232-1988

DATE PREPARED: 02/24/92

PRODUCT NAME: RENUZIT Fresh 'n Dry Air & Fabric Deodorizer-Aerosol . 1301Z 1305Z 1306Z 91301 91305 91306 91307

N.F.P.A. 704: HEALTH: O FLAMMABILITY: 4 REACTIVITY:

This product is labeled in accordance with regulations administered by the Consumer Product Safety Commission because the use pattern and exposure in the workplace are generally consistent with those experienced by consumers. In certain respects, the requirements of the Occupational Safety and Health Administration applicable to the drafting of this Material Safety Data Sheet may differ from the requirements of the CPSC and as a result, this MSDS may contain additional information to that found on the label.

SECTION II

HAZARDOUS INGREDIENTS/IDENTITY INFORMATION

HAZARDOUS COMPONENT:

A-46 Propellant Blend (Propane & Butane)

PERCENT 99

CAS NUMBER: Unassigned

ACGIH TLV: Not Established .

OSHA PEL: Not Established

MANUFACTURER PEL: Not Established

ORIGINAL DOCUMENT - END OF PAGE

SECTION III

PHYSICAL/CHEMICAL CHARACTERISTICS

BOILING POINT:

(degrees F)

212

2921

SPECIFIC GRAVITY: 0.6

(Water=1)

VAPOR PRESSURE: (mm Hg)

MELTING POINT: Not Applicable

(degrees F)

VAPOR DENSITY: (Air=1)

1.9

EVAPORATION RATE: >1

(BuAc=1)

SOLUBILITY IN WATER: 100

рΗ

7

APPEARANCE AND ODOR: Clear gas with various odors.

SECTION IV

FIRE AND EXPLOSION HAZARD DATA

PRINTED: 2000-05-30

MATERIAL SAFETY DATA SHEET BOOK PAGE: CHEMICAL ID: 437900 MSDS ID: 437900 PRODUCT NAME: Renuzit Fresh N Dry Air & Fabric Deodori 650

FACILITY: 316400 Northwest District

.ASH POINT: (degrees F)

-123

METHOD USED: TCC

FLAMMABLE LIMITS: LEL (V/V%) 1.8

UEL (V/V%) 9.5

EXTINGUISHING MEDIA:

In case of fire, use water fog, foam, dry chemical, carbon dioxide, or other Class B extinguishing agents.

SPECIAL FIRE

FIGHTING PROCEDURES:

Firefighters and others exposed to combustion

by-products should wear full protective

equipment, including pressure demand self-contained breathing apparatus and turnout

equipment.

Keep containers cool with fog stream. Use shield to protect personnel against bursting

or venting containers.

UNUSUAL FIRE AND EXPLOSION HAZARD: FLAMMABLE. Do not spray on hot surfaces or

into flames or spark or arc producing

equipment. Level III Aerosol (NFPA 30B).

ORIGINAL DOCUMENT - END OF PAGE

SECTION V

REACTIVITY DATA

STABILITY:

Stable

CONDITIONS TO AVOID:

None

INCOMPATIBILITY:

Not Applicable

(MATERIALS TO AVOID)

DECOMPOSITION

Not Applicable

PRODUCTS:

HAZ. POLYMERIZATION:

Will not occur

CONDITIONS TO AVOID: Not Applicable

SECTION VI

HEALTH HAZARD DATA

ROUTES OF ENTRY FOR SYSTEMIC POISONING:

INHALATION:

Systemic poisoning by this route is not expected.

ABSORPTION:

Systemic poisoning by this route is not expected.

INGESTION:

Systemic poisoning by this route is not expected.

HEALTH HAZARDS:

May freeze skin or eyes if sprayed at close range.

PRINTED: 2000-05-30

MATERIAL SAFETY DATA SHEET BOOK PAGE: 651

CHEMICAL ID: 437900 MSDS ID: 437900 PRODUCT NAME: Renuzit Fresh N Dry Air & Fabric Deodori

FACILITY: 316400 Northwest District

FUTE AND CHRONIC)

CARCINGGENICITY NTP: No Ingredients on List

IARC: No Ingredients on List No Ingredients on List DTHER:

Prolonged direct physical exposure to aerosol spray may result in blistering, whitish fingertips, redness and/or loss of sensation. SIGNS AND SYMPTOMS

OF EXPOSURE:

MEDICAL CONDITIONS None known.

AGGRAVATED BY **EXPOSURE:**

AID PROCEDURES:

EMERGENCY AND FIRST Skin: If irritation occurs, wash with lukewarm water. Contact Poison Center or physician.

ORIGINAL DOCUMENT - END OF PAGE

SECTION VII

PRECAUTIONS FOR SAFE HANDLING AND USE

RELEASE OR SPILL ACTIONS:

In case of spill or leak, remove ignition sources, evacuate enclosed space until gas has dispersed.

Flush area with water.

WASTE DISPOSAL METHOD:

Dispose only in accordance with applicable federal, state and local laws and regulations.

PRECAUTIONS IN HANDLING AND

STORAGE:

Do not store above 120 F. Exposure to sunlight or

heat may cause bursting. Do not incinerate or

puncture.

OTHER PRECAUTIONS:

Do not spray into flame, appliances, or vacuum

bags. In use keep finger behind spray opening.

SECTION VIII

CONTROL MEASURES

RESPIRATORY PROTECTION: Not required when used according to label

instructions.

VENTILATION:

Not required when used according to label

instructions.

SKIN PROTECTION:

Not required when used according to label

instructions.

EYE PROTECTION:

Not required when used according to label

instructions.

WORK/HYGIENIC PRACTICES:

Not required when used according to label

instructions.

PRINTED: 2000-05-30

MATERIAL SAFETY DATA SHEET BOOK PAGE: CHEMICAL ID: 437900 MSDS ID: 437900 PRODUCT NAME: Renuzit Fresh N Dry Air & Fabric Deodori 652

FACILITY: 316400 Northwest District

This product contains a chemical subject to the reporting requirements of Section 313 of Title III of the Superfund Amendments and Reauthorization Act of 1986 and 40 CFR, Part 372.

DRIGINAL DOCUMENT - END OF PAGE

**** END OF MATERIAL SAFETY DATA SHEET FOR: Renuzit Fresh N Dry Air ***

PRINTED: 2000-05-30